A.	GENERAL INFORMATION	
1.	Street Address of the School: Ave. Munos Bivera, Esq. Gll Y Toste Hate	Dey !
	city: San Juan state: Puer to Bico zip:	
2	( , - 1 1 1 0	
2.	, ,	
3.	Date of inspection: 0//15/20 to 0//16/20	
4.	Inspector's Name: José A. Fernandez Polo, PE, José C. Ortiz,	EI
В.	BUILDING SITE INSPECTION	
5.	Utility Service Safety:	
detecte	RTANT-Immediately following an earthquake, check the entire property, especially near appliances, for the smell of gas. If gas led, turn off the gas at the meter where it enters the house. Locate and repair leaks before turning gas back on. If the gas odor he gas has been shut off, vacate the building and contact the gas utility company immediately.	odor is persists
	RTANT-Before entering a damaged, vacant building verify that gas is off. Check the gas meter for damage and position of main either a manual valve or a seismically-activated gas shut-off valve. Do not enter the building if gas odor is detected.	gas
	a. Odor of natural gas leakage?  YES NO b. Downed powerlines? YES NO	
6.	Surrounding topography: (©check one)  Flat  Gently sloping (easily walkable)  Steeply sloping (difficult or impossible to walk in some areas)	
7.	Building pad: (@checkone)	
	Flat	
	Terraced or multilevel	
	Gently sloping (less than 4-foot ground surface elevation difference across house)	
	Steeply sloping (greater than 4-foot ground surface elevation difference across house)	
8.	Geotechnical Issues: (if yes, provide description and photos)	NO
	a. New cracks in the ground?	
	b. Signs of fresh cracking in or movement of hardscape?	W W
	c. Signs of fresh cracking in or movement of retaining walls?	W
	d. Patterns of cracking that extend through the ground surface, hardscape, and improvements?	
	e. Evidence of sand boils or other fresh-appearing deposits of sand or mud?	4
	f. Unusual slumping, rising, or bulging of the ground surface?	
	g. Evidence of rock falls or slope instability above site?	U U
	h. Ground movement or wet areas indicating possible broken underground utility lines?	P
	i. Other phenomena (e.g., septic tanks surfacing, differential settlement, ground consolidation)?	

B. 9.	BUILDING SITE INSPECTION (continued)  Evidence of earthquake-induced permanent ground deformation in the immediate vicinity of property?	YE the	s NO	
C. 10. 11.	GENERAL BUILDING INFORMATION  Safety Assessment Tag: (3 check one) None Green Yellow  (others): Yellow Red  a) Year of original construction (best estimate): 9/30/74 b) Total square footage (best estimate): 597, 813 544  Have any repairs, modifications, or demolition been performed since the earthquake?	Red YE	S NO	
13.	Building configuration:  a. Single story  b. Combination one and two story  c. Full two story  d. Three story  e. Split level  f. Typical  g. Other, describe  Exterior wall finish:  a. Stucco  b. Panel siding	d to foundatio	on	
15.	c. Metal siding  cl. Masonry veneer  e. Other, describe			

D.		EXTERIOR BUILDING INSPECTION			
	19.	General: (if yes, provide description and photos)	YES	NO	N/A
		a. Collapse, partial collapse, or building off foundation?		W	
		b. Obvious lean in any story?		9	
20.		Exterior walls: (if yes, provide description and photos)			
		a. Fresh cracking at corners of door and window openings?		4	
		b. Fresh cracking at building corners?			
		c. Door or window openings racked out of square?		4	
		d. Broken glass in windows or doors?		U	
		e. Wall leaning?		4	
		f. Bulging or delamination of stucco?	П	4	
		g. Pattern of cracking that extends from the ground surface, through foundation, and wall?		y	
		h. Evidence of recent relative movement at mudsill line?		P	
		i. At locations where the exterior stucco is continuous from the framing down over the			
		foundation, is there cracking of stucco along the mudsill level accompanied by indications			
		of permanent displacement (sliding) of the building relative to the foundation?			
		j. Collapse, partial collapse, or separation of masonry veneer?		W	
		k. Severe cracking, separations, or offsets at building irregularities?		4	
21.		Foundation: (if yes, provide description and photos)			
		a. Fresh cracking of exposed perimeter foundation?			
		b. Relative movement between slab and footing in "two-pour" slab-on-grade foundations?	П	O'	
		c. Ask homeowner if any earthquake retrofits have been done to the home?		W	
		If Y describe:			
		d. If the answer to c is Y, were bolts added to connect the home to the foundation?		П	4
		e. If the answer to c is Y, were plywood or sheathing added to any cripple walls under the home?			

D.	EXTERIOR BUILDING INSPECTION (continued)		•	
	22. Kitchen Hook (if yes, provide description and photos)	YES	NO	N/A
	a. Present on external wall?		V	
	b. Present at internal location?		V	
	c. Collapse or partial collapse?		V	
	d. Visible damage or cracking?		V	
	e. Visible tilting or separation from building?		V	
	f. Shifted or loose and displaced		V	
	g. Deterioration or deformation		V	
23.	Roof: (if yes. provide description and photos)			
	a. Shifted or dislodged or concrete damage?		V	
	b. Impact damage to roof from falling object?		W	
	c. Displaced rooftop HVAC units?		U .	П
	d. Significantly sagging roof ridgelines?		W	
	e. Signs of movement between rafter tails and wall finishes at eaves?			
	f Buckled/dislodged flashing or tearing of roof membrane, roof/wall intersections in split		W.	
	level buildings, additions, or other building irregularities?			
	g. Tearing of roof membrane or deck waterproofing at re-entrant corners?	П	O .	. 🗆
	h. Toppling, shifting, or damage/leakage at refrigerant and electrical lines of rooftop			
	mechanical equipment?			
	i. Shifting of or damage to solar panels?			4

D.	EXTERIOR BUILDING INSPECTION (continued)			
24.	Attached or abutting improvements: (if yes, provide description and photos)	YES	NO	N/A
	a. Collapse. partial collapse, or separation of attached porches, carports, Gazebos,	or		
	awnings?			
	b. Evidence of recent settlement or displacement of exterior steps, patios,		e e	
	or walkways relative to the building?			_
	c. Signs of movement between building floor and/ or exterior hardscape or retaining		V	
	wall along the uphill side of hon steeply sloping sites?		U	
	d. Toppling, shifting, or damage/leakage at refrigerant and electrical lines of			
	air conditioning condenser unit(s)?			
25.	Independent exterior improvements: (if yes, provide description and photos)			
	a. Damaged detached gazebo?		U	4
	b. Damage to fences / privacy walls?		4	
	c. Damage to retaining walls?		4	
	d, Damage to walkway?			П
	e. Evidence of leakage from water supply lines?			
	f. Toppling, shifting, or damage/leakage at fuel connection of propane tanks?	П	THE THE	П
	g. Others damage			
E.	INTERIOR INSPECTION			
26.	General information			
	a. If interior access not possible, identify reason b. Typical wall an			
	i. Red tag ii. Hazardous materials iii. Plaster	on gypsum lath		
	iii. Other hazardous condition, iii. Plaster	on wood lath		
	describe iv. Other, d	lescribe		
	iv. Other describe			

E.	INTERIOR INSPECTION (continued)			
27.	Walls: (if yes, provide description and photos)	YES	NO	N/A
	a. Fresh cracking, buckling, spalling, or detachment of interior wall finish at corners of		U	
	door and window openings?			
	b. Fresh cracking of wall finishes at wall corners or wall/ceiling intersections?		4	
	c. Door or window openings racked out of square?		Y	
	d. Wall leaning?		V	
	e. Pattern of cracking that extends from the floor slab through the wall?		W	
	f. Movement or sliding of walls relative to the floor?		W	
	g. Severe cracking, separations, or offsets at building irregularities?		W	
	h. Doors damaged, difficult to operate, or inoperable?			
	i. Windows damaged, difficult to operate, or inoperable?			
28.	Ceilings: (if yes, provide description and photos)			
	a. Collapse of ceiling finish?		U	
	b. Fresh cracking of ceiling finishes, especially at re-entrant corners; cracks along corner		V	
	bead at stairwell openings; cracking or tearing of finishes at ceiling/wall juncture; or multiple			
	"nail pops"?			
	c. Damage to ceiling finishes in vicinity of corridors or commons places?			П
	d. Separations or cracks in ceiling finishes at split-levels, re-entrant corners,		4	
	additions, appendages, or other building discontinuities?			
	e. Water damage or evidence of recent leakage from plumbing lines or roofing?		U	

E.	INTERIOR INSPECTION (continued)			
29.	Floors: (if yes, provide description and photos)	YES	NO	N/A
	a. Evidence of recent sloping, sagging, settlement or displacement of floors?		V	
	b. In slab-on-grade locations, fresh cracking of floor slab or floor finishes?		V	
	c. Significant sagging or unusual bounciness of floors frames?		V	
	d. Separations or cracks in floor finishes at split-levels, re-entrant corners, additions,		Y	
	appendages, or other building discontinuities?			
	e. Signs of movement between floor and exterior hardscape or retaining wall along		U	
	the uphill side of homes on steeply sloping sites?			
	f. A pattern of fresh cracks, gaps, or joint separations in floor finishes?			
	g. Impact damage to floor finishes from falling contents?	Ш		Ш
30.	Mechanical systems: (if yes, provide description and photos)			Ш
	a. Displaced connection of appliance flues connected to chimneys?	П		П
	b. Toppling, shifting, leakage from tank, leakage from water connections displaced flue	Ц		
	connection or damage/leakage at gas line or electrical connection of water heater?			
	c. Shifting, damage/leakage at gas line, flue connection, electrical connection, refrigerant line,	Ц		
	and condensate drain connection of furnace or air conditioning fan-coil unit?	Ш	U	Ц
	d. Damage to gas line of gas stoves or gas fueled clothes dryers?			
	e. Damage to toilets?	Ш	Lu	
	f. Decreased or restricted water pressure at appliances, faucets, or toilets?	П		
	g. Toppling or shifting of free-standing wood stove and/or flue?			П
	h. Toppling, shifting, damage/leakage at fuel connection of fuel oil tank?	П	U	П
	i. Other Damage in the dining room	П	T	П
	j. Damage near the gas tank			
	j. Damage near the gas tank			

E.	INTERIOR INSPECTION (continued)			
31.	Architectural woodwork and special finishes: (if yes, provide description and photos)	YES	NO	N/A
	a. Shifting of or damage to kitchen or bathroom cabinetry?		W.	
	b. Impact damage to countertops from falling objects?		U	
	c. Cracking of ceramic tile in showers or tub/shower enclosures consistent with		U	
arate Administration and the state of the st	earthquake damage to adjacent wall finishes?			
F.	CONTINGENTINSPECTIONS			
		YES	NO	N/A
32.	Retaining Tank Wall damage?		4	
33.	Water tank or other field subterranean structure		4	

G.	RECOMENDACIÓN
	Hora de Entrada 8:00 am M Hora de Salida de 5:00 pm lu Inspección:  Edificio: Centro Judicial San Juan Código:
	Edificio: Centro Judicial San Juan Código:
	Municipio: San Juan Fecha de Inspección: 01/15/20
	Abrir (Verde)
	Abrir Parcialmente (Amarillo)
	No Abrir (Rojo)
	그는 그는 그는 그는 가장 바라를 하는 것이다. 이렇게 되어 사용하는 것이 없는 것이 없는 것이다.
	Comentarios:
	Ver Socumen to Adjunto
- 8	
	t has been prepared for the exclusive use by the here-in stated client or their agent. It should be noted that, as
equested,	this report is based solely on a visual inspection of the as-is facility for the purpose of assessing the presence of a structural damage resulting from the seismic event of January 07, 2020 which may affect its structural condition
ompared	to that prior to said event. The inspection may not reveal all deficiencies; all components and conditions which by
nclude mo	of their location are concealed, camouflaged or difficult to inspect are excluded from the report. Report does not aterials testing, soil studies, structural studies or analysis of structure design. The determination of the structural of the existing facility to meet the applicable design and construction building codes requirements, as well as
leveloping	g recommendations for the rehabilitation of the facility will require a more extensive investigation than that one to be conducted and reported herein.
	Nombre (Letra de Molde)
	Nombre (Letra de Molde)  5238
	Firma # Licencia # Licencia UNGENIERO CONTROL PER CIADO
/	
	LIC. 5238

G. RE	COMENDACIÓN
Hora a Ins	ra de Entrada 8:00 am Hara de Salida de 4:00 par la Inspección:
Edi	ificio: Centro Judicial San Juan Código: 10,70 nicipio: Fecha de Inspección: 0//16/20
Abrii	ir (Verde)
	ir Parcialmente (Amarillo)  Abrir (Rojo)
Come	nentarios:
	Ver documento Adjunto
is renort has	been prepared for the exclusive use by the here-in stated client or their agent. It should be noted that, as
quested, this r	report is based solely on a visual inspection of the as-is facility for the purpose of assessing the presence of ctural damage resulting from the seismic event of January 07, 2020 which may affect its structural condition
mpared to tha	at prior to said event. The inspection may not reveal all deficiencies; all components and conditions which by eir location are concealed, camouflaged or difficult to inspect are excluded from the report. Report does not
clude material lequacy of the	els testing, soil studies, structural studies or analysis of structure design. The determination of the structural existing facility to meet the applicable design and construction building codes requirements, as well as immendations for the rehabilitation of the facility will require a more extensive investigation than that one
quested to be	conducted and reported herein.
Nomb	bre (Letra de Molde)
Firma	5238
	S SEIGENCIADO )
	Page 9 of 9
	Page 9 of 9


#### Comentarios:

- 1. Gritas en el pavimento son por el deterioro del mismo por el paso del tiempo.
- 2. En la losa de piso del sótano, se presentan unas grietas. Las mima responde al comportamiento natural de la losa. Además, la misma no le hicieron las juntas en el proceso de vertido. No se presentan asentamientos diferenciales entre la losa de piso y los componentes estructurales de la misma.
- 3. En los techos de los anexos norte y sur, presentan unos elementos (barandas) prefabricadas en la parte superior de los parapetos del perímetro de las estructuras. Recomendamos que estos elementos sean sustituidos ya que en un movimiento abrupto de la estructura podrían desprenderse y golpear a las personas que estén saliendo de la estructura. Se deben tomar las medidas de seguridad necesarias para proteger a los peatones en lo que corrige la situación.
- 4. En varios lugares del edificio, se presentan algunas grietas menores en el empañetado. Las mismas no afectan la integridad de la estructura, no obstante, recomendamos se corrijan. Se realizaron varias exploratorias y se descartó que las mismas fuesen estructurales.
- 5. En el área de la Secretaria Regional en el segundo nivel del Anexo sur, se presenta una grieta en la columna, la misma responde a la unión de la columna y un "chase" en bloques que se creó para la tubería de escape del generador de emergencia. Esto no representa ningún daño estructural.
- 6. En la azotea del edificio, se ubican tres (3) torres de enfriamiento. Las estructuras en acero de las mismas se encuentran corroídas. Aunque esta situación no afecta la operación y apertura del edificio, recomendamos se evalúe esta condición con un lng. Estructural y reemplazar estos elementos.
- 7. Se puede observar que el sistema de impermeabilización del edificio principal está en mal estado. En varios lugares se puede notar acumulación de agua y desprendimiento del mismo. Recomendamos su reparación, esto para evitar el deterioro del edificio, en especial las áreas con filtraciones en el nivel once (11).

#### Personal Presente en la Inspección

- 1. Samuel Velázquez
- 2. Mayra Cordero Romero- Directora Administración
- 3. Gilberto Figueroa -Jefe De Alguaciles
- 4. Daniel Padilla Vélez Ingeniero Rama Judicial
- 5. Jorge Rodríguez- Administración AEP

## **Fotos**



Exploratoria en Columna. (Grieta en el Empañetado no daño estructural.




Tope en los parapetos anexos norte y sur. Recomendamos reemplazar.



Base de las Torres de Enfriamiento.



Sistema de Impermeabilización Afectado.



## FERPO CONSULTING, PSC.

P.O. Box 361300, San Juan, Puerto Rico 00936-1300 Tel. (787) 505-4981

Building Name:	Centrofudiciai san juan #1070
Inspector (s):	fox A. Firmances Polo, PE fox Corky Est
CERTIFICATIO	N:
I, Jose A. Fernan	dez Polo, Principal Engineer, License 5238, certify that: I have revie

I, Jose A. Fernandez Polo, Principal Engineer, License 5238, certify that: I have reviewed and discussed this ocular inspection report with the engineer that inspected the building, and based on my knowledge and experience, I agree with their conclusion

Abrir	(Verde)		W
Abrir Parcia	almente	(Amerillo)	
No Abrir	(Rojo)		

This report has been prepared for the exclusive use by the here-in stated client or their agent. It should be noted that, as requested, this report is based solely on a visual inspection of the as-is facility for the purpose of assessing the presence of significant structural damage resulting from the seismic event of January 07, 2020 which may affect its structural condition compared to that prior to said event. The inspection may not reveal all deficiencies; all components and conditions which by the nature of their location are concealed, camouflaged or difficult to inspect are excluded from the report. Report does not include materials testing, soil studies, structural studies or analysis of structure design. The determination of the structural adequacy of the existing facility to meet the applicable design and construction building codes requirements, as well as developing recommendations for the rehabilitation of the facility will require a more extensive investigation than that one requested to be conducted and reported herein.

Name: José A. Fernandez Polo, PE

Signature LIC. 5238

PUERTO RICO